

Job Information

Job #: 140050 Date: June 27, 2019

Priority: — Authorized OT: No Authorized by: Terry f

Customer Information

Name: Big river Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: KSB Enclosure: Open Drop Proof Enclosure Type image

(ODP)
Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Rated Amps: Rated Voltage:

Phase: Cycles:


Special design: No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Water

Shaft rotation: CCW Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

None

Shaft runout(TIR-Inbound): .0005

Type of grounding device:

present?:

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 7324

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Other Bearing ODE Size: 211e

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: Good

Lubrication brand inbound: Unknown Thermal Protection device ODE: Good

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: Watery

Seals DE type: Other Seals Image:

Seals DE size:

Seals DE (inbound) condition: Bad

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301

CENTRAL ARKANSAS

N/A



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings: T1-6

Length of leads: 2ft REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: T1-6
Lug type: Regular

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Acceptable





Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition: Wet

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal

Protection ODE:

Stator test results: Salvageable

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301



Conclusion

Component Failure

Ground fault

Cause of Failure

Water in winding

Comments

Mechanical seal failed ok MSN pump causing water and oil to trip motor

Service Tech name: Terry

Service Tech signature:

