

Job Information

140146 Job #: Date: July 10, 2019

Priority: Authorized OT: No Authorized by:

Customer Information

Name: **LRHISPEED** Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: US Enclosure: Weather Protected **Enclosure Type image**

I (WPI)

BF47A

Serial#: H040S2BLF Model#:

Service Factor: 324TPH 1.15 Frame:

Horsepower/kW: 40 Rated RPM: 1775

Rated Amps: 103/51.5 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: CW Contaminant(s) Amt: None

Shaft grounding device present?: No Contaminant Image:

Shaft runout(TIR-Inbound): N/A

Type of grounding device:

Bearings DE: Loose Bearings DE make: FAG

Insulated: No Bearing DE Size: 7220BEP

Bearings ODE: Loose Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 62112Z

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/4 Grease Cond. DE: Other

Grease Amt ODE: 1/4 Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: Other

Seals Image 2:

Shaft Image:



Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Endbell Image:



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings: 1,2,3,p1,p2

Length of leads: 12" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Good Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: —







AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

56

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Fail

Stator type: Factory If other, stator type:

Stator condition: Single phase If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)


Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Other Lead jumper Image. :

If other, leads/jumpers:



Kelly Adta



Conclusion

Component Failure

Single phased.

Cause of Failure

Single phased.

Comments

Service Tech name: Kelly Felts

Service Tech signature:

Fax 901-873-5301