

Job Information

Job #:	140239				Date:	July 25, 2019
Priority:	3	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Hi-Speed (LR)		Reason:	
Contact:		Motor#:		PO#:
Application:	Direct Drive	Special notes:		

Name Plate Information

Manufacturer:	U.S Electrical	Enclosure :	Totally Enclosed Fan Cooled	Enclosu	re Type image
Serial#:	R932- A11A268R032M	Model#:	R932		
Service Factor:	1.15	Frame:	445T		
Horsepower/kW:	150	Rated RPM:	1780		
Rated Amps:	174/211	Rated Voltage:	460/380	W.	
Phase:	3	Cycles:	60		
Special design:	No				
Nameplate	DE	ODE	F1	F2	Тор



VUEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Water
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:	N/A		
Shaft runout(TIR-Inbound):	.001		

Bearings DE:	Worn	Bearings DE make:	
Insulated:	No	Bearing DE Size:	6220
Bearings ODE:	Worn	Bearings ODE make:	NACHI
Bearing Type:	Ball	Bearing ODE Size:	6313
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Watery
Grease Amt ODE:	Full	Grease Cond. ODE:	Watery
Seals DE type:	N/A	Seals Image:	
Seals DE size:	N/A		
Seals DE (inbound) condition :	N/A		
		Seals Image 2:	
Seals ODE type:	Slinger		
Seals ODE size:	N/A		
Seals ODE (inbound) condition :	N/A		
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



S PARA

Mechanical Inspection (Continued)

Air Gap M	leaurements (N/A on Sin	Does Air Gap Meet Customer or EASA spec(<10% variation)?		
N/A	DE @ 0	N/A	ODE @ 0	_
N/A	DE @ 90	N/A	ODE @ 90	
N/A	DE @ 180	N/A	ODE @ 180	
N/A	DE @ 270	N/A	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:	1-6	
Length of leads:	6"	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	2AWG	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:	Round	Connections As Rec	ceived: All Black	
Lug Condition:	Good	Т	Ferminal	Lugs
Lug size:	N/A			
Lug Attachment:	Acceptable			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum	,	Rotor
Rotor Condition:	Ok _	Num rotor bars: 58	
		Num broken bars: 0	
Rotor Test Results			
Visual: Pass		Growler: Pass Single	e phase: Pass
Stator type:	Factory	If other, stator type:	N/A
Stator condition:	Ok	If other, stator condition:	N/A
Failure location:	Other	If other, stator failure:	N/A
Stator Image:		Failure Image:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Wind	ing color:	Like new	Winding	g image Wi	nding Thermal Pro	otection: No		
Winding c	ondition :	Solid						
	Thermal ction DE:	_						
	Thermal	_						
Stator tes	st results:	Rewind						
Megs incomi	ng: Good	d	Surge incoming:	Good	Hi-pot incom	ning: Good		
Winding Re	esistance In	coming						
	Phase	es A to B	Phases B to C	Phases C	to A Re	sistive imbalance		
Incoming	0.26		0.26	0.26	0			
	Leads/jumpe	ers: Ok		Lead jumper	r Image. :			
If other,	leads/jumpe	ers: N/A						

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Moisture in motor

Cause of Failure

Bad bearings

Comments

Needs washed, baked, and new bearings installed.

Service Tech name: Erich Sodam

Service Tech signature:

FDO

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301