

Job Information

Job #: 140418 Date: August 16, 2019

Priority: — Authorized OT: No Authorized by: Terry

Customer Information

Name: Ktg Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Mario cotta Enclosure : Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#: 80-mot

Service Factor: Frame:

Horsepower/kW: .45kw Rated RPM: 1580

Rated Amps: 1.3 Rated Voltage: 380

Phase: Cycles:

No

Nameplate DE ODE F1 F2 Top

Not Available









CENTRAL ARKANSAS

Special design:



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Dirt Yes

> Contaminant(s) Amt: Shaft rotation: Bi-directional Other

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: NSK

Insulated: Bearing DE Size: 6007 No

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Bearing ODE Size: Ball 6002

Bearings Retainer: Thermal Protection: Yes Yes

Retainer condition: Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: Thermal Overloads

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type:

N/A

Seals Image 2:

Not Available

Seals ODE size:

Shaft damage cause: None Shaft Image:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

N/A

Fan:

N/A

Frame cond.:

Good

Not Available Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings: 1-6

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 2overloads ohms .2 Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Acceptable Available



Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 21.5 21.5 0.5

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

Bearings

Cause of Failure

Bad bearings may need machine work

Comments

Service Tech name: Terry

Service Tech signature:

7-0