

### **Job Information**

Job #: 140423 Date: August 15, 2019

Priority: — Authorized OT: No Authorized by: Terry f

## **Customer Information**

Name: Ktg Reason: New bearings

Contact: Motor#: PO#:

Application: – Special notes:

### **Name Plate Information**

Manufacturer: Isgev Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 1407368 Model#:

Service Factor: Frame:

Horsepower/kW: 7.5 Rated RPM: 1780

Rated Amps: 9.2 Rated Voltage: 480

Phase: Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:











CENTRAL ARKANSAS



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: CCW Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 308

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 308

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Not Available

Thermal Protection



## **Mechanical Inspection (Continued)**

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Shaft damage cause:

Seals Image 2:

Seals ODE type: N/A Not Available

Seals ODE size:

Shaft Image:

None



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good

Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

**✓** None

,

Other missing parts





## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

**AC Electrical Inspection** 

Number of leads: 6 Terminal Markings: 1-6

Length of leads: 2inches REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 1-6
Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Not Not Lug Attachment: Acceptable Available Available



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:





No



# **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.2 0.2 0.2 0.4

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Stable Not Available



### Conclusion

### **Component Failure**

Motor came in needing new bearings

#### **Cause of Failure**

Rust formed inside end bells and bearings

#### Comments

Cleaned parts and stator, applied new bearings reassemble and test ran in same day

Service Tech name: Terry f

Service Tech signature: