

Job Information

Job #:	140499				Date:	August 28, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	KTG	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Mario cotta	Enclosure :	Open Drop Proof (ODP)	Enclos	ure Type image
Serial#:	00000/01	Model#:	IMB3	ASSI	
Service Factor:	1.0	Frame:	IP44		
Horsepower/kW:	.45 KW	Rated RPM:	1590	15	Print P
Rated Amps:	1.3	Rated Voltage:	230/380/460		Contraction of the second s
Phase:	3	Cycles:	85/102/148		
Special design:	No				
Nameplate	DE	ODE	F1	F2	Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):	.0005		

Bearings DE:	Worn	Bearings DE make:	
Insulated:	No	Bearing DE Size:	6007Z
Bearings ODE:	Worn	Bearings ODE make:	NSK
Bearing Type:	Ball	Bearing ODE Size:	6002Z
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	Thermocouple

Bearing Type Image



Bearing Make Image

Bearing Retainer Image



Thermal Protection



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	Thermal Overloads
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	Thermal Overloads
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	0	Grease Cond. DE:	Other
Grease Amt ODE:	1/4	Grease Cond. ODE:	Other
Seals DE type: Seals DE size: Seals DE (inbound) condition :	N/A	Seals Image:	Not Available under maintenance
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition :	N/A	Seals Image 2:	Not Available under mainternance
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:	None			
Length of leads:	3ft	REF: NEMA Stds. Markings Identifie	MG 1-2009, Rev. 1- d By Color:	2010, 2.41-Terminal		
Size of leads:	18	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:	Pin	Connections As Received: Y				
Lug Condition:	Good	Те	erminal	Lugs		
Lug size:						
Lug Attachment:	-					

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum		Rotor
Rotor Condition:	Ok	Num rotor bars: 44 Num broken bars: 0	
Rotor Test Results			
Visual: Pass		Growler: Pass Single phase	se: Pass
Stator type:	Factory	If other, stator type:	
Stator condition:	Ok	If other, stator condition:	
Failure location:	Other	If other, stator failure: None	9
Stator Image:		Failure Image:	Not Available under maintenauce

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding co	olor:	Like new	Winc	ling image	Winding Therm	al Protection:	Yes
Winding condition	on :	Solid	r			1.00	0
Winding Thermal Protection DE:							
Winding Therr Protection OI		_	The second secon	1 .			
Stator test resu	ılts:	Rewind					
Megs incoming:	Goo	d	Surge incoming:	Good	Hi-pot i	ncoming: Ge	bod
Winding Resista	nce In	coming					
	Phas	es A to B	Phases B to	C Pha	ses C to A	Resistive imb	alance
Incoming	0		0	0			
Leads	/jumpe	ers: Ok		Lead ji	umper Image. :		
If other, leads	/jumpe	ers:					

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Stator winding

Cause of Failure

An open circuit in winding caused by 1or more broken wires.

Comments

Service Tech name: Kev F

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301