

#### **Job Information**

Job #: 140555 Date: September 5,

2019

Priority: — Authorized OT: No Authorized by:

# **Customer Information**

Name: West Memphis Steel Reason:

Contact: Motor#: PO#:

Application: – Special notes:

#### **Name Plate Information**

Manufacturer: Lesson Enclosure: Totally Enclosed Enclosure Type image

Non-Ventilated

Serial#: 11614100 Model#: C6T17NZ88A

Service Factor: 1.0 Frame: 56Y

Horsepower/kW: 1 Rated RPM: 1725/1425

Rated Amps: 3.2/3.5/1.6/1.9 Rated Voltage: 230/190/460/380

Phase: 3 Cycles: 60/50

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301



## **Mechanical Inspection**

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Worn

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: 

Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6203-2Z/C3GJN

Bearings Retainer: No Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

#### Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

Other



Thermal Protection



Seals Image 2:



#### **Mechanical Inspection (Continued)**

Lubrication Type: Other Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: 0 Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:


N/A

Fan:

N/A

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

☐ None



Other missing parts

Drive end housing



### **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

### **AC Electrical Inspection**

Number of leads: 9 Terminal Markings: 1,2,3,4,5,6,7,8,9

Length of leads: 12" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 18 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 460

Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —





# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 45

Num broken bars: 0

Rotor

#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type:

Stator condition: Roast-out If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







### **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:



Stator test results: Rewind

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

**Winding Resistance Incoming** 

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:



WEST TENNESSEE

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

CENTRAL ARKANSAS

Telly Hollo



#### Conclusion

**Component Failure** 

**Bearings** 

**Cause of Failure** 

Bearings locked up

**Comments** 

Service Tech name: Kelly Felts

Service Tech signature:

Fax 901-873-5301