

Job Information

Job #: 140557 Date: September 12,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: KTG Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Mario cotta Enclosure : Open Drop Proof Enclosure Type image

Model#:

(ODP)

Service Factor: Frame:

Horsepower/kW: .46 Rated RPM:

Rated Amps: Rated Voltage: 230/380/460

Phase: 3 Cycles:

Special design: No

Serial#:

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes None

> Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: Bearing DE Size: 60007 No

Bearings ODE: Worn Bearings ODE make: **FAG**

Bearing Type: Bearing ODE Size: Ball 60002

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Thermal Protection Type:

Bearing Type Image











WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

x 901-873-5301

Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: Thermal Overloads

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: Thermal Overloads

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 1/4 Grease Cond. DE: New

Grease Amt ODE: 1/4 Grease Cond. ODE: New

Seals DE type: Seals Image: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: Shaft Image: None

N/A



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

Ok



Fan: O

Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 4' REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 18 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown 3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received:

Lug Condition: Good Terminal Lugs

Lug size:

Lug type:

Lug Attachment: —





Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure: None

Stator Image: Failure Image:





Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:









Conclusion

Component Failure		
Cause of Failure		
Comments		
Service Tech name:		
Service Tech signature:		