

Job Information

Job #: 140872 Date: October 11, 2019

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Sonoco Reason:

Contact: Motor#: 140872 PO#:

Application: **Direct Drive** Special notes:

Name Plate Information

Manufacturer: Reliance Enclosure: Totally Enclosed **Enclosure Type image**

Fan Cooled 52mn36552 Serial#: Model#: P36G5552E

Service Factor: 1.15 Frame: 365TDZ

Horsepower/kW: 100 Rated RPM: 1770

Rated Amps: 240/120 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Grease

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): .001

Type of grounding device:

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 65RU03T30X

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 65BC03T30X

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

Ok

Fan:

Ok

Frame cond.:

Good

Not Available





Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Endbell Image:



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 5 ft

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 6 awg

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type: None

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 47

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition: Ok

Failure location: Other If other, stator failure: No failure

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 7.3 1.8 6.3 0.3

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

Cause of Failure

Bearings

Comments

Service Tech name: Jeremy Yarbrough

Service Tech signature:

& Harrangl