

Job Information

Job #: 140878 Date: October 11, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: St Judes Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Marathon Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Model#: 9VB215TTFS6001

GWR113I

Service Factor: 1.15 Frame: 215T

Horsepower/kW: 10 Rated RPM: 3535

Rated Amps: 23.6/11.8 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No

.0001

present?: No Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NTN

Insulated: No Bearing DE Size: 6307ZZ

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Ball Bearing ODE Size: 6206ZZ

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Not Available

Thermal Protection

Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

Not Available

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

Ok

Fan: Ok

Frame cond.:

Good

Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

■ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 6" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 14 awg 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 9,6 8,5 7,4, 1 2 3

Lug Condition: — Terminal Lugs

Lug size:

Lug type:

None

Lug Attachment: —



Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 30

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:

Not Available



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.8818 0.8816 0.8821 0.1

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Bearings

Cause of Failure

Comments

Spring washer on ode end

Service Tech name: Jeremy Yarbrough

Service Tech signature:

Market