

Job Information

Job #: 140882 Date: October 21,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: KTG Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Mario-cotta Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 48691/20 Model#:

Service Factor: Frame:

Horsepower/kW: .45 Rated RPM: 1200

Rated Amps: 1.3 Rated Voltage: 380

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Other Yes

> Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device Yes

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: Bearing DE Size: 6007-2Z No

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Bearing ODE Size: Ball 6002Z

Bearings Retainer: Thermal Protection: No No

Retainer condition: Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: 0 Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

N/A

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

WEST TENNESSEE



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A



N/A

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Endbell Image:



Other missing parts

One broken bolt in bolt hole.



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 68"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: 18

P2-Brown 2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Terminal

Lug size:

Lug Attachment:

Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Questionable If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Bad Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 20.82 20.84 20.81 0.1

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Bearings

Cause of Failure

Bearings bad

Comments

Service Tech name: Kelly Felts

Service Tech signature:

Fax 901-873-5301

Kelly Tel