

Job Information

Job #: 141089 Date: November 5,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Valero Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Continental Electric Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 782336 Model#: Job #141089

Service Factor: Frame: NPV505P

Horsepower/kW: 75 Rated RPM: 1185

Rated Amps: 90 Rated Voltage: 440

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Oil

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 314S

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 314K

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: Watery

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

N/A

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 3 Terminal Markings: Brown, White, Orange

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition:

Connections As Received: 440

Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:







AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 57

Num broken bars: 0 Rotor



Rotor Test Results

Rotor Condition:

Visual: Single phase: **Pass** Growler: **Pass Pass**

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure: Oil grease and dirt

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind





No

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.061710 0.061820 0.061760 0.2

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:



Kelly Fels



Conclusion

Component Failure

Bearings

Cause of Failure

Dirt oil on windings, water in bearings

Comments

Service Tech name: Kelly Felts

Service Tech signature:

Fax 901-873-5301