

### **Job Information**

Job #: 141090 Date: November 5,

2019

Priority: — Authorized OT: No Authorized by:

### **Customer Information**

Name: Ktg Reason:

Contact: Motor#: 141090 PO#:

Application: – Special notes:

### **Name Plate Information**

Manufacturer: Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 168920 Model#:

Service Factor: 1.15 Frame: 509LL

Horsepower/kW: 250 Rated RPM: 1195

Rated Amps: 57 Rated Voltage: 2300

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No

present?: No Contaminant Image:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: NTN

Insulated: No Bearing DE Size: 6318

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Ball Bearing ODE Size: 6315

Bearings Retainer: No Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





## **Mechanical Inspection (Continued)**

Lubrication Type: Oil Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition :

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None

Slinger

Shaft Image:





# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan:

N/A

Frame cond.:

Good



an.

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts



## **Mechanical Inspection (Continued)**

#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

### **AC Electrical Inspection**

Number of leads: 6 Terminal Markings: 1,1,2,2,3,3

Length of leads: 21" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 6awg 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: 2300

Lug type:

Lug Condition: Warn

Lug size:

Lug Attachment: —

Terminal



Lugs





# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 86

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Connection If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**


Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 1.096100 2.191 1.096100 74.9

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:



Stone Rubbard



### **Conclusion**

**Component Failure** 

Winding

**Cause of Failure** 

Lead connection failure

**Comments** 

Service Tech name: Stone Hubbard

Service Tech signature:

Fax 901-873-5301