

Job Information

Job #: 141122 Date: November 7,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Process &Power Reason:

Contact: Motor#: 141122 PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Reliance Enclosure: Open Drop Proof Enclosure Type image

(ODP)
Serial#: O1MON94279 Model#: P4OGO416D

GOO1 ED

Service Factor: 1.15 Frame: 405TDZ

Horsepower/kW: 150 Rated RPM: 1775

Rated Amps: 179 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













CENTRAL ARKANSAS



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: CCW Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): .001

Type of grounding device:

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: NU316E

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6316C3

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Other

Grease Amt ODE: Full Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

Ok



Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

✓ J-Box cover

O-rings

✓ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings: 1-2-3-4-5-6

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 4'

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 2

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Open

Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 42

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition: Ok

Failure location: Other If other, stator failure: N/A

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 13 13 0.07

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Bearings

Cause of Failure

Dirt and dust build up

Comments

Clean up wash and bake Order 2 new new bearings NU316E -6316C3 Spacers go under the baffles Snap rings in both ends

Service Tech name: Michael

Service Tech signature: