

Job Information

Job #: 141304 Date: December 11,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: USG Reason:

Contact: Motor#: 141304 PO#:

Application: Radial Load Special notes:

Name Plate Information

Manufacturer: TOSHIBA Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: 37hp Rated RPM: 1740

Rated Amps: 66 Rated Voltage: 400

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Cup

Shaft grounding device No Contaminant Image:

Worn

present?:

Insulated: No Bearing DE Size: 6313

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6212

Bearings Retainer: No Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

SKF



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Charred

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A Seals Image:

Seals DE size:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:





Frame cond.:

Good







Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 12 Terminal Markings: 1-12

Length of leads: 12" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 8 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 400 Lug type: Reg

Lug Condition: Good Terminal Lugs

Lug size: 3/8

Lug Attachment: Acceptable



Failure Image:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 39

Num broken bars: 0

Rotor



Rotor Test Results

Stator Image:

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure: Pass





No



AC Electrical Inspection (Continued)


Winding color: Like new Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 17 17 17 0.2

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Bearings and sleeve in ode

Cause of Failure

Dust inside the stator

Comments

New bearings and clean up 6313-6212 Bore and bush ODE

Service Tech name: Michael

Service Tech signature: