

Job Information

Job #: 141674 Date: January 27,

2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Hershey Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Nord Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled Serial#: 34211602 Model#: Sk90s/4cus

Service Factor: 1.15 Frame: 90s

Horsepower/kW: 1.5 Rated RPM: 1660

Rated Amps: 4.84/2.42 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Other

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?:

Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6305Z

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6205-c-zz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Unknown Thermal Protection device ODE: N/A

Lubrication brand outbound: Unknown

> Grease Amt DE: Full Grease Cond. DE: Other

Grease Amt ODE: Full Grease Cond. ODE: Watery

Seals DE type: Seals Image: Other

Seals DE size: 25 40 7

Seals DE (inbound) condition: Good

Seals ODE type:

Seals Image 2:

Seals ODE size: 25 37 5

Seals ODE (inbound) condition Good

Other

Shaft damage cause: Shaft Image: None



Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A



Fan: Broken



Frame cond.: Good



Motor Mount Position:

Horizontal/Flange mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

✓ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings: 1-9

Length of leads: 6" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: High voltage Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: —





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 28

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)


Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Charred

Winding Thermal ___ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Other Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Winding

Cause of Failure

Overload

Comments

Winding roasted

Service Tech name: Shawn

Service Tech signature:

Show Splanning to the state of the state of