

### **Job Information**

Job #:	141840				Date:	February 18, 2020
Priority:	1A Rush/OT	Authorized OT:	No	Authorized by:		

### **Customer Information**

Name:	Ktg		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

Manufacturer:	Abb	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	615527	Model#:		
Service Factor:		Frame:		
Horsepower/kW:	Kw421	Rated RPM:		
Rated Amps:	624	Rated Voltage:	480	
Phase:		Cycles:		
Special design:	No			

Nameplate

DE

ODE

F2



Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301







## **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Grease
Shaft rotation:	_	Contaminant(s) Amt:	Full
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	324
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	319
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

#### Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

#### **Bearing Retainer Image**



#### **Thermal Protection**





# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	Good
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	1/2	Grease Cond. DE:	Watery
Grease Amt ODE:	1/2	Grease Cond. ODE:	Gritty
Seals DE type: Seals DE size: Seals DE (inbound) condition :	N/A	Seals Image:	
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition :	N/A	Seals Image 2:	



Shaft Image:

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Shaft damage cause:

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

None



### **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:




Water jacket: N/A



Fan: Ok







Motor Mount Position:

Horizontal/Foot mount



Missing parts?

J-Box cover	O-rings	J-Box
HH cover	Glands	V None

Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


# **AC Electrical Inspection**

Number of leads:	6	Terminal Markings:	T1-6	
Length of leads:	6inches	REF: NEMA Stds Markings Identifie	a. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	AWG 1	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	_	4-Yellow	8-Red	
Lug type:		Connections As Rec	eived:	
Lug Condition:	Good	т	erminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding	color:	Still has color	Winding	g image	Winding Therma	Protection:	Yes
Winding con	dition :	Mushy					
Winding Th Protectio	hermal on DE:	Good					
Winding Th Protection		_	1995				Y
Stator test r	esults:	Rewind					
Megs incoming:	: Goo	d	Surge incoming:	Good	Hi-pot in	coming:	Good
Winding Resis	stance In	coming					
	Phas	es A to B	Phases B to C	Phase	es C to A	Resistive in	mbalance
Incoming	2		2	2		2	
Lea	ads/jumpo	ers: Ok		Lead jun	nper Image. :		

If other, leads/jumpers:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### Conclusion

#### **Component Failure**

Overheated

#### **Cause of Failure**

Dirt paper heat lack of grease

#### Comments

Lack of grease motor overheated

Service Tech name: Terry

#### Service Tech signature:



WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301