

Job Informatio

Job #: 142607 Date: June 10, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: BASF Reason:

Contact: Motor#: 142607 PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Baldor Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: P44G3939 Model#:

Service Factor: 1.15 Frame: 444T

Horsepower/kW: 125 HP Rated RPM: 1785

Rated Amps: 144 Rated Voltage: 460

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6318

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6318

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: Grease Cond. ODE: Other

Seals DE type: Seals Image: N/A

Seals DE size: N//A

Seals DE (inbound) condition: N/A

Seals ODE type:

Seals Image 2:

Seals ODE size: N/A

Seals ODE (inbound) condition N/A

Slinger

Shaft damage cause: Shaft Image: None



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

Ok



Ok

Frame cond.:

Good



-an:

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings: 1-2-3

Length of leads: 17 inches REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1AWG 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug size:

Good

Lug Condition:

Lug Attachment: —

Terminal



Lugs



Rotor



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 58

Num broken bars: 0

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:





Conclusion

Component Failure

Bearings failed due to lack of grease

Cause of Failure

Lack of lubrication

Comments

Service Tech name: Jesus

Service Tech signature:

ADP!