

Job Information

Job #: 142749 Date: June 30, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: USG Reason:

Contact: Motor#: 142749 PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: SIEMENS Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 1LA04474SE41C Model#:

Service Factor: 1.15 Frame: 447T

Horsepower/kW: 200HP Rated RPM: 1785

Rated Amps: 223 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

Bearings DE:

Worn

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Insulated: No Bearing DE Size: NU320C3

Bearings ODE: Worn Bearings ODE make: Koyo

Bearing Type: Ball Bearing ODE Size: 6316ZZC3

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

Koyo



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Other

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image

Shaft Image:

Seals Image 2:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings: 123

Length of leads: 24" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 36

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.021760 0.023110 0.021640 6.6

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failu	ıre
-----------------	-----

Shaft

Cause of Failure

Comments

Shaft broken

Service Tech name: Shawn

Service Tech signature:

Gun