

#### MILLINGTON, TN LITTLE ROCK, AR

## **Job Information**


Job #:	142845				Date:	July 9, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

#### **Customer Information**

Name:	Ktg	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

#### **Name Plate Information**

Manufacturer:	Star electric	Enclosure :	Open Drop Proof (ODP)	Enclosure Type imag
Serial#:		Model#:		104
Service Factor:		Frame:		
Horsepower/kW:	1.1	Rated RPM:	600	
Rated Amps:	2.5	Rated Voltage:	440	
Phase:	3	Cycles:	60	
Special design:	No			





Nameplate

DE

ODE

F1

F2













Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### MILLINGTON, TN LITTLE ROCK, AR

## **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Dirt
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	306
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	306
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

#### Bearing Type Image



Bearing Make Image




#### WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





#### **Thermal Protection**





# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Charred
Grease Amt ODE:	Full	Grease Cond. ODE:	Charred
			_
Seals DE type:	N/A	Seals Image:	
Seals DE size:			
Seals DE (inbound) condition :			
		Seals Image 2:	
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# MILLINGTON, TN LITTLE ROCK, AR

# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:	N/A		Fan:	Ok	Frame co	nd.: Good
Motor Mount Pos	sition: Horizontal/F	oot mount			Endbell type:	Single piece
Missing parts	\$?				Endbell Image:	1/20
J-Box cover	O-rings	J-Box				
HH cover	Glands	None				
Other missing p	arts					

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

## **AC Electrical Inspection**


Number of leads:	3	Terminal Markings:	123	
Length of leads:	3"	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Rec	ceived:	
Lug Condition:	Good	Т	erminal	Lugs
Lug size: Lug Attachment:	_			
			Di	

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## MILLINGTON, TN LITTLE ROCK, AR

#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### MILLINGTON, TN LITTLE ROCK, AR

# **AC Electrical Inspection (Continued)**

Winding co	olor:	Dull black	Winding	g image	Winding Therma	I Protection:	No
Winding condit	ion :	Charred					NY.
Winding The Protection	rmal DE:	_					
Winding The Protection C		_	2			- Barris	
Stator test res	ults:	Rewind					
Megs incoming:	Bad		Surge incoming:	Bad	Hi-pot in	coming: B	ad
Winding Resista	ance In	coming					
	Phase	es A to B	Phases B to C	Phase	es C to A	Resistive imb	balance
Incoming	3.116	6	13.626	12.3	52	108.00	
Lead If other, lead	s/jumpe s/jumpe			Lead jur	nper Image. :		

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

#### **Component Failure**

Winding

Cause of Failure

Overheated

#### Comments

Winding roasted and full of dirt. Bearing grease charred and dirty

Service Tech name: Shawn

Service Tech signature:

Sh

WEST TENNESSEE 7030 Ryburn Drive

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301