

### **Job Information**

Job #:	93808				Date:	January 4, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

#### **Customer Information**

Name:	ЗМ		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

Manufacturer:	Ectopic	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type i
Serial#:		Model#:		
Service Factor:		Frame:	256T	
Horsepower/kW:	10	Rated RPM:	1170	
Rated Amps:	27.4/13.7	Rated Voltage:	230/460	
Phase:	3	Cycles:	60	
Special design:	No			

#### image



Nameplate

DE

ODE

F1

F2

Тор













WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	Dirt
Shaft rotation:	_	Contaminant(s) Amt:	Full
Shaft grounding device present?: Type of grounding device:	No	Contaminant Image:	

Shaft runout(TIR-Inbound):

Bearings DE:	Locked up	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	6309
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6309
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

#### Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Bearing Retainer Image



**Thermal Protection** 



# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Hard
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type: Seals DE size: Seals DE (inbound) condition :	Slinger 45-65-8	Seals Image:	
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition :	Slinger 45-65-8	Seals Image 2:	
			1



Shaft Image:

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Shaft damage cause:

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Other



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:	N/A	Fan:	Ok	Frame co	ond.: Good
Motor Mount Po	sition: Horizontal/F	oot mount		Endbell type:	Single piece
Missing parts	s?			Endbell Image:	100-
J-Box cover	o-rings	J-Box			
HH cover	Glands	None None			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

# **AC Electrical Inspection**

Number of leads:	12	Terminal Markings:	1-12	
Length of leads:	8"	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	14	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Rec	ceived: 460 volt	
Lug Condition:	_	т	erminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type:	Cast Aluminum			Rotor
Rotor Condition:	OkN	Num rotor bars: lum broken bars:		
Rotor Test Results				
Visual: Pass	Growler	Pass	Single phase:	Pass
Stator type: Stator condition:	Factory Ok	If other, stator ty If other, stator condit		
Failure location:	In slot	If other, stator fail		
Stator Image:				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding color:	Like new	Winding	g image	Winding Therma	I Protection:	Yes
Winding condition :	Solid				MotorAnalyzer 2	SCHLETON
Winding Thermal Protection DE:	_				Time An image 12 pages   Terminal and terminal a	60% CTK 1   233 Team 1   234 Contract 1   235 Team 1   236 Contract 1   236 Contract 1   236 Contract 1   237 Contract 1   238 Contract 1   239 Contract 1   239 Contract 1   239 Contract 1
Winding Thermal Protection ODE:	_				the state of the	
Stator test results:	Salvageable					
Megs incoming: Go	ood	Surge incoming:	Good	Hi-pot in	coming: G	ood
Winding Resistance	Incoming					
Pha	ases A to B	Phases B to C	Phase	s C to A	Resistive imb	balance
Incoming 0.7	702	0.704	0.705		0.2	
Leads/jum If other, leads/jum			Lead ju	mper Image:		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

#### **Component Failure**

DE Bearing

**Cause of Failure** 

DE Bearing contamination

#### Comments

De bearing locked up causing inner race to spin on shaft. Will have to repair DE journal and DE EB housing fit

Service Tech name: L Me

L McDonald

Service Tech signature:

LMD mall

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301