

Job Information

94050 Job #: Date: March 12, 2018

Priority: Authorized OT: No Authorized by:

Customer Information

Name: **AIMS** Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Open Drop Proof **Enclosure Type image**

(ODP)

1LA5209-2BA91-Serial#: Model#:

ZT01

Service Factor: 200L Frame:

Horsepower/kW: 37KW Rated RPM: 3565

Rated Amps: 59 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Worn

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: — Contaminant(s) Amt: Cup

Shaft grounding device No Contaminant Image:

present?:

Insulated: No Bearing DE Size: 6212-C4

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6212-C4

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

Other



Thermal Protection

Not Available



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition :

Seals Image 2:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Not



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good

Not Available







Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

Length of leads: 36" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Acceptable





Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Charred

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Good Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.168 0.238 0.407 70.9

Leads/jumpers: Ok Lead jumper Image. :

Not If other, leads/jumpers: Available

Part It Man



Conclusion

Component Failure

Phase to. Phase

Cause of Failure

Comments

Service Tech name: RHR

Service Tech signature:

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

7030 Ryburn Drive

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254