

Job Information

Job #: 94060 Date: March 13, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Falcon. Jet Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Ingersol. Rand Enclosure : Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#: 22178354

Service Factor: Frame: 326T

Horsepower/kW: 50 Rated RPM: 1780

Rated Amps: 126/72.4/63 Rated Voltage: 230/400/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6312C3

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6212C3

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Thermal Protection

Not Available



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size: N/a Not Available

Seals DE (inbound) condition:

Seals Image 2:

Seals ODE type: Slinger

Seals ODE size: N/a

Seals ODE (inbound) condition N/a

Shaft damage cause: None Shaft Image:

Not



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

Ok

Fan:

Ok

Frame cond.:

Good

Not Available

Not Available

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

Γ

O-rings

☐ J-Box

☐ HH cover

Glands

■ None

Other missing parts

Out to the second of the secon



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 9"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 8 P2-Brown

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:







AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Stator Image:

Single phase: Visual: **Pass** Growler: Pass Pass

Stator type: If other, stator type: Factory

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Not Available

Failure Image:



AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.250 0.159 0.185 32.5

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Cause of Failure

Comments

Service Tech name: RHR

Service Tech signature: