

Job Information

Job #:	94095				Date:	March 20, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Performance foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Open Drop Proof (ODP)	E
Serial#:	F1098	Model#:	06F172W352G1	
Service Factor:	1.15	Frame:	184CZ	
Horsepower/kW:	5	Rated RPM:	1750	
Rated Amps:	13/6.5	Rated Voltage:	230/460	
Phase:	3	Cycles:	60	
Special design:	No			

Enclosure Type image





DE

ODE



















WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Other
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	NSK
Insulated:	No	Bearing DE Size:	6207 2Z
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6205 2Z
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image

nage Bearin

Bearing Retainer Image Ther

Thermal Protection

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Charred
Grease Amt ODE:	Full	Grease Cond. ODE:	Charred
Seals DE type:	Slinger		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	Slinger		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Water jacket: Ok Fan: Ok Frame cond.: Good Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece Missing parts? Endbell Image: O-rings J-Box J-Box cover HH cover None Glands Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	_	Terminal Markings:			
Length of leads:		REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	_	4-Yellow	8-Red		
Lug type:		Connections As Re	eceived:		
Lug Condition:	-		Terminal	Lugs	
Lug size:					
Lug Attachment:	_				

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	ı image	Winding The	Winding Thermal Protection:		
Winding condition :	Solid						
Winding Thermal Protection DE:	_						
Winding Thermal Protection ODE:	_						
Stator test results:	Rewind						
Megs incoming: Goo	d	Surge incoming:	Good	Hi-p	ot incoming:	Good	
Winding Resistance Ir	coming						
Phas	es A to B	Phases B to C		Phases C to A	Resistive	imbalance	
Incoming							
Leads/jump	ers: Ok						

If other, leads/jumpers:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Excessive amounts of grease inside stator. Also bearings were worn and needed to be replaced.

Comments

Motor initially checked bad on incoming test. However after washing and baking out the stator the windings tested good, and show no signs of visible damage.

Service Tech name: Terrence Holland

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301