

### **Job Information**

Job #: 94158 Date:

Priority: — Authorized OT: No Authorized by:

### **Customer Information**

Name: ENTERGY WHITE BLUFF Reason:

Contact: Motor#: PO#:

Application: – Special notes:

### **Name Plate Information**

Manufacturer: Westinghouse Enclosure: Totally Enclosed Enclosure Type image

Non-Ventilated

Serial#: 7905N Model#: TBAH

Service Factor: 1.0 Frame: 231TZ

Horsepower/kW: 1.1 Rated RPM: 870

Rated Amps: 4.6/2.3 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: Yes

Nameplate DE ODE F1 F2 Top















# **Mechanical Inspection**

Type of grounding device:

Shaft runout(TIR-Inbound):

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Carbon

Shaft rotation: Bi-directional Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

present?:

Bearings DE: Locked up Bearings DE make: Other

Insulated: No Bearing DE Size: 6207ZZ

Bearings ODE: Fell Apart Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6206ZZ

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



## **Mechanical Inspection (Continued)**

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

Other missing parts





## **Mechanical Inspection (Continued)**

#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90** 

DE @ 180 **ODE @ 180** 

DE @ 270 **ODE @ 270** 

### **AC Electrical Inspection**

Number of leads: 9 Terminal Markings: 1-9

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 6" Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 18

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Bad

Connections As Received: 460 Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type:

Stator condition: Roast-out If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







# **AC Electrical Inspection (Continued)**

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal Protection DE:

Bad

Winding Thermal Protection ODE:

Bad

Stator test results: Rewind

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

**Winding Resistance Incoming** 

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

Ok

Lead jumper Image:



If other, leads/jumpers:



### Conclusion

**Component Failure** 

**Cause of Failure** 

#### **Comments**

Stator complete roast out drive bearing locked up ode bearing carrage was broke ode bearing fit bad

Service Tech name: Robert Wiley

Service Tech signature:

Fax 901-873-5301