

## **Job Information**

Job #:	94229			Date:	May 16, 2018	
Priority:	_	Authorized OT:	No	Authorized by:		

## **Customer Information**

Name:	Entergy whitebluff		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

## **Name Plate Information**

Manufacturer:	Limit torque	Enclosure :	Open Drop Proof (ODP)	Er
Serial#:	713107-SA	Model#:		
Service Factor:		Frame:		
Horsepower/kW:	.7	Rated RPM:	1700	
Rated Amps:	4.6/2.3	Rated Voltage:	230/460	
Phase:	3	Cycles:	60	
Special design:	No			

#### Enclosure Type image



Nameplate

DE

ODE

F1

F2

Тор







WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	_	Contaminant(s):	None
Shaft rotation:	_	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			1 TR
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	Коуо
Insulated:	No	Bearing DE Size:	6203/2Z
Bearings ODE:	Worn	Bearings ODE make:	Коуо
Bearing Type:	Ball	Bearing ODE Size:	6203/2Z
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

#### Bearing Type Image



7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Bearing Make Image

Bearing Retainer Image

**Thermal Protection** 





# **Mechanical Inspection (Continued)**

_	Thermal Protection device DE:	Grease	Lubrication Type:
_	Thermal Protection device ODE:	Unknown	Lubrication brand inbound:
		Unknown	Lubrication brand outbound:
New	Grease Cond. DE:	0	Grease Amt DE:
New	Grease Cond. ODE:	0	Grease Amt ODE:
	Seals Image:	N/A	Seals DE type:
C			Seals DE size:
			Seals DE (inbound) condition :
		N/A	Seals ODE type:
			Seals ODE size:
			Seals ODE (inbound) condition
	Shaft Image:	None	Shaft damage cause:



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:	N/A	
---------------	-----	--

Fan:

N/A

Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

Missing parts?

J-Box cover O-rings HH cover Glands

J-Box None

#### Other missing parts

Endbell type:

Single piece

Endbell Image:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single P	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


## **AC Electrical Inspection**

Number of leads:	—	Terminal Markings:			
Length of leads:		REF: NEMA Std Markings Identif	s. MG 1-2009, Rev. 1- ied By Color:	2010, 2.41-Terminal	
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	_	4-Yellow	8-Red		
Lug type:		Connections As Re	eceived:		
Lug Condition:	_		Terminal	Lugs	
Lug size:					
Lug Attachment:	-				

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding	color:	Dull black	Winding	g image	Winding Therma	I Protection: No
Winding cond	ition :	Brittle				
Winding The Protection		_	and the second se	A CONTRACTOR		
Winding The Protection		_				
Stator test re	sults:	Rewind				
Megs incoming:	Bad		Surge incoming:	Bad	Hi-pot in	coming: Bad
Winding Resis	tance Ir	ncoming				
	Phas	es A to B	Phases B to C	Phase	es C to A	Resistive imbalance
Incoming	16		10	15		34.5
Lea	ds/jump	ers: Ok		Lead ju	Imper Image:	
If other, lea	ds/jump	ers:				

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### Conclusion

**Component Failure** 

**Cause of Failure** 

Bearings/windings

#### Comments

Bearings were completely locked up from rust. Windings tested bad.

Service Tech name:

**Terrence Holland** 

Service Tech signature:

Alla 1 en

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301