

Job Information

Job #: 94249 Date: May 10, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Sage Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Teikoku Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: FA-1092A-1 Model#: 42-316F4AM-608T

S1-E

Service Factor: Frame:

Horsepower/kW: 6.2 Rated RPM: 3600

Rated Amps: 12 Rated Voltage: 460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:









Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Other Bearings DE make: Other

Insulated: No Bearing DE Size:

Bearings ODE: Other Bearings ODE make: Other

Bearing Type: Other Bearing ODE Size:

Bearings Retainer: No Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/4 Grease Cond. DE: New

Grease Amt ODE: 1/4 Grease Cond. ODE: New

Seals DE type: Slinger

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts?

J-Box cover O-rings J-Box

HH cover Glands None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: — Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:



Failure Image:





AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

1 1010011011 221

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

1.559

1.560

1.550

0

Leads/jumpers:

Ok

Lead jumper Image:



If other, leads/jumpers:



Conclusion

Component Failure

Cause of Failure

Motor direction indicator ohms out bad.

Comments

Motor ran and tested good. Motor direction indicator checks bad.

Service Tech name: Terrence Holland

Service Tech signature:

CENTRAL ARKANSAS

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

WEST TENNESSEE

7030 Ryburn Drive

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254