

Job Information

Job #: 94258 Date: May 17, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Mohawk industries Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Carver pump Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#: WKM50H-8

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Rated Amps: N/a Rated Voltage:

Phase: N/a Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top









Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Timken

Insulated: No Bearing DE Size: 72200c

Bearings ODE: Worn Bearings ODE make: Timken

Bearing Type: Tapered roller Bearing ODE Size: 72200c

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 0 Grease Cond. DE: New

Grease Amt ODE: 0 Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

Shaft damage cause: None

Seals Image 2:



Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: — Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Lug type: Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok _

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	j image	Winding	g Thermal Protection	: Yes
Winding condition:	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:	-					
Stator test results:	Rewind					
Megs incoming: Good	d	Surge incoming:	Good		Hi-pot incoming:	Good
Winding Resistance In	coming					
Phase	es A to B	Phases B to C		Phases C to A	Resistive	imbalance
Incoming						
Leads/jumpe	ers: Ok					
If other, leads/jumpe	ers:					



Conclusion

Com	pone	nt F	ailure
-----	------	------	--------

Cause of Failure

Seals/multiple impellers and housing assemblies

Comments

Final stage impeller, and stages 10,9,8,7,6 bad. Also housing assemblies #9&8 worn. Shaft seal surface worn.

Service Tech name: Terrence Holland

Service Tech signature: