

Job Information

Job #: 94344 Date: May 25, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: SYNOVOS-L"OREAL Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: VELOCITA Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 80746001 Model#:

Service Factor: Frame:

Horsepower/kW: 27KW Rated RPM:

Rated Amps: Rated Voltage: 480

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6312ZZC3

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6312ZZC3

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Seals Image: Other

Seals DE size: 60 80 8

Seals DE (inbound) condition: Worn

Seals ODE type:

Seals Image 2:

Seals ODE size: 60 80 8

Seals ODE (inbound) condition Worn

Other

Shaft damage cause: Shaft Image: None





Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A Fan: Missing Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 —

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings: 1-6

Length of leads: 16" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 12 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: WYE 480
Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

0.211

0.217

0.217

2.8

Leads/jumpers:

Ok

Lead jumper Image:



If other, leads/jumpers:

2012 Dilory



Conclusion

Component Failure

Cause of Failure

Comments

Bearings seals wash and bake

Service Tech name: Robert Wiley

Service Tech signature: