

Job Information

Job #: 94375 Date: June 22, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: American rail Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Leeson Enclosure: Totally Enclosed Enclosure Type image Fan Cooled

Serial#: G150031.60 Model#: C365T17F06D

Service Factor: 1.25 Frame: 365T

Horsepower/kW: 75 Rated RPM: 1780

Rated Amps: 173/86.5 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:











WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6313

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6313

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE size:

Seals DE (inbound) condition:

Seals Image 2:

Seals ODE type: N/A

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.:

Good

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 11"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: P2-Brown

2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug size:

Lug Condition:

Lug Attachment: Acceptable

Good

Terminal



Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding ima

Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable





Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 8.37 86.7 88.4 3.4

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Com	pone	nt F	ailure
-----	------	------	--------

Bearings

Cause of Failure

Bearings had contaminated grease in them.

Comments

Motor tested and ran good. Recommend reconditioning motor and return to service.

Service Tech name: Terrence Holland

Service Tech signature: