

Job Information

Job #:	94396				Date:	July 6, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	LR QUARRIES		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Dodge	Enclosure :	Totally Enclosed Non-Ventilated	Enclosure Type image
Serial#:		Model#:	NON-ventilated	
Service Factor:		Frame:		
Horsepower/kW:		Rated RPM:		
Rated Amps:		Rated Voltage:		
Phase:		Cycles:		
Special design:	No			



DE

ODE

F1

F2

Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	Water
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			Contraction of the second

Bearings DE:	Fell Apart	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Tapered roller	Bearing ODE Size:	
Bearings Retainer:	Yes	Thermal Protection:	Yes

Retainer condition:

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Thermal Protection Type:

_

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

_	Thermal Protection device DE:	Oil	Lubrication Type:
_	Thermal Protection device ODE:	Unknown	Lubrication brand inbound:
		Unknown	Lubrication brand outbound:
New	Grease Cond. DE:	Full	Grease Amt DE:
New	Grease Cond. ODE:	Full	Grease Amt ODE:
	Seals Image:	Other	Seals DE type: Seals DE size: Seals DE (inbound) condition :
	Seals Image 2:	Other	Seals ODE type: Seals ODE size:

Seals ODE (inbound) condition :

Shaft damage cause:

Other

Shaft Image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water	jacket:	N/A
-------	---------	-----

N/A

Fan:

n: N/A

Frame cond.: Good



Motor Mount Position	: Horizontal/F	oot mount	Endbell type:	Single piece
Missing parts?			Endbell Image:	
J-Box cover	O-rings	J-Box		
HH cover	Glands	None None		Const.
Other missing parts				
Bolts				

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	_	Terminal Markings:		
Length of leads:		REF: NEMA Std Markings Identif	s. MG 1-2009, Rev. 1- ied By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	_	4-Yellow	8-Red	
Lug type:		Connections As Re	eceived:	
Lug Condition:	-		Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor	Туре:	Cast Aluminum					Rotor
Rotor Conc	dition:	Ok		Nu	um rotor bars:		
Rotor Condition:		ÖK	Num broken bars:				
Rotor Test	Results						
Visual: I	Pass		Grow	ler:	Pass	Single phase:	Pass
Stator	type:	Factory			If other, stator	type:	
Stator conc	dition:	Ok			If other, stator cond	ition:	
Failure loca	ation:	In slot			If other, stator fa	ilure:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding image		Winding Th	ermal Protection	: Yes
Winding condition :	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:	_					
Stator test results:	Rewind					
Megs incoming: Goo	d	Surge incoming:	Good	Hi-ŗ	pot incoming:	Good
Winding Resistance Ir	ncoming					
Phas	es A to B	Phases B to C		Phases C to A	Resistive	imbalance
Incoming						
Leads/jump	ers: Ok					

If other, leads/jumpers:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Seal failure caused the gearbox to leak out the oil and fill with water and the bearings locked up

Comments

Bearings seals input shaft and seal surface

Service Tech name:

Robert Wiley

Service Tech signature:

st Wiley

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301