

Job Information

Job #: 94403 Date: June 19, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Uniting Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: To shiva Enclosure: Totally Enclosed Enclosure Type image Fan Cooled

Serial#: 40805460 Model#: B3004FLF4BMQ

Service Factor: 1.15 Frame: N587UZ

Horsepower/kW: 300 Rated RPM: 1780

Rated Amps: 350 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): N/A

Type of grounding device:

Bearings DE: Worn Bearings DE make: Koyo

Insulated: No Bearing DE Size: Nu 324R

Bearings ODE: Worn Bearings ODE make: Koyo

Bearing Type: Ball Bearing ODE Size: 6320ZX

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Bad Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: N/A Seals Image:

Seals DE size:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

:

Shaft damage cause: Other Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

✓ J-Box cover

O-rings

✓ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 26" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned
4-Yellow 8-Red


Lead condition: Bad 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Painted

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

11.6

10.8

10.9

5.8

Leads/jumpers:

Replace

Lead jumper Image.:



If other, leads/jumpers:



Conclusion

Component Failure

D.e. Bearing

Cause of Failure

Grease in bearing was very hard and contaminated leading to bearing failure.

Comments

Frosting inside o.d.e. Bearing

Service Tech name: Terrence Holland

Service Tech signature:

CENTRAL ARKANSAS

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

WEST TENNESSEE

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254