

### **Job Information**

Job #: 94467 Date: July 10, 2018

Priority: — Authorized OT: No Authorized by:

## **Customer Information**

Name: A.I.M. Reason:

Contact: Motor#: PO#:

Application: — Special notes: No name plate attached.

### **Name Plate Information**

Manufacturer: Enclosure : Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Rated Amps: Rated Voltage:

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













CENTRAL ARKANSAS



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes None

> Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: Other

Insulated: Bearing DE Size: No 6309(2ea)

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Bearing ODE Size: Ball 6306

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





## **Mechanical Inspection (Continued)**

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: N/A Grease Cond. DE: Other

Grease Amt ODE: N/A Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition :

Seals Image 2:

Shaft Image:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254

Slinger



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket: C

Ok



Fan: C

Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None



Other missing parts

Seals



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90** 

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270** 

## **AC Electrical Inspection**

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 13"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: P2-Brown

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Replace





Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 39

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







# **AC Electrical Inspection (Continued)**

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Mushy

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.615 0.617 0.778 26.1

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:



2/15/



### Conclusion

Component Failure	Com	oon	ient	raii	lure
-------------------	-----	-----	------	------	------

Unknown

#### **Cause of Failure**

Unknown

#### **Comments**

Stator windings show ground after wash and bake. Because the old seals were not with the assembly, they could not be evaluated as a possible cause contributing to motor failure.

Service Tech name: Terrence Holland

Service Tech signature:

WEST TENNESSEE CENTRAL ARKANSAS
7030 Ryburn Drive 6812 Lindsey Rd.

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254