

Job Information

Job #: 94621 Date: August 20, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Flake Board Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled Serial#: 1LA02864FC21 Model#: RGZ

Service Factor: 1.15 Frame: 286T

Horsepower/kW: 30 Rated RPM: 1760

Rated Amps: 74.2/37.1 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6310 2Rs

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6210 2RS

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.:





Good

Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

THI Cover ___ Clands ___ N





Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 9 Terminal Markings: 1-9

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 12"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition:

Connections As Received: Lug type:

Lug Condition: Good Terminal

Lug size:

Lug Attachment:

Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 36

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Single phase: **Pass** Growler: Pass **Pass**

Stator type: If other, stator type: Factory

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.332 0.327 0.334 1.3

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Com	ponent	Failure
-----	--------	----------------

Cause of Failure

DE AND ODE HOUSING FITS BAD BOTH BEARINGS HAVE FLUTTING

Comments

RESLEEVE HOUSING FITS AND INSTAL AGEIS RING SHAFT SIZE 2.361

Service Tech name: Robert Wiley

Service Tech signature:

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 Robert D'Ilers