

Job Information

Job #: 94634 Date: August 23, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Be is Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Tascunt Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 133345 Model#: 160CD 4/2

Service Factor: Frame:

Horsepower/kW: 8.9 Rated RPM: 1550

Rated Amps: Rated Voltage: 230/460

Phase: Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6308 2RS

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6305 2RS

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Unknown Thermal Protection device ODE:

Lubrication brand outbound: Unknown

> Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: Grease Cond. ODE: Other

Seals DE type: Seals Image: Other

Seals DE size: 40 52 7

Seals DE (inbound) condition: Bad

Seals ODE type:

Seals Image 2:

Seals ODE size: 25 35 7

Seals ODE (inbound) condition Bad

Other

Shaft damage cause: Shaft Image: None



Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A



Fan: Ok



Endbell Image:

Frame cond.:





Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

✓ J-Box cover

O-rings

☐ J-Box

HH cover

/er

Glands

☐ None



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 —

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings: 1-9

Length of leads: 8" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 1.505 1.504 1.505 0.0

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:



2017 Wiley



Conclusion

Component Failure

Clutch coil caught fire and burned the Tac leads

Cause of Failure

Comments

Need new clutch coil tac fan cover bearings and seals resleeve De end bell

Service Tech name: Robert Wiley

Service Tech signature: