

Job Information

Job #:	94645				Date:	August 17, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information


Name:	Riceland Foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	L96-2	Model#:	1LA04496SE42
Service Factor:	1.15	Frame:	449TS
Horsepower/kW:	200	Rated RPM:	1185
Rated Amps:	222	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			Not Available

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	6320
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6316
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 Bearing Make Image



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 ineman folection type.

Bearing Retainer Image



Thermal Protection

Not Available



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Hard
Grease Amt ODE:	Full	Grease Cond. ODE:	Hard
Seals DE type:	N/A	Seals Image:	
Seals DE size:			Not Available
Seals DE (inbound) condition :			
		Seals Image 2:	
Seals ODE type:	N/A	Seals maye 2.	Not
Seals ODE size:			Available
Seals ODE (inbound) condition :			
Shaft damage cause:	Other	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single P	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings	5:		
Length of leads:	12"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	Good	4-Yellow	8-Red		
Lug type:		Connections As F	Received:		
Lug Condition:	Good		Terminal	Lugs	
Lug size:			Not		
Lug Attachment:	Acceptable	А	vailable		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum		Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:	
Rotor Test Results			
Visual: Pass	Gro	owler: Pass	Single phase: Pass
Stator type:	Factory	If other, stator ty	/pe:
Stator condition:	Ok	If other, stator condit	ion:
Failure location:	Other	If other, stator fail	ure:
Stator Image:		Failure Ima	^{age:} Not Available

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Painted	Winding	g image	Winding Thermal	Protection:	No
Winding condition :	Solid	No. 10			Ν	lot
Winding Thermal Protection DE:	_				Avai	lot ilable
Winding Thermal Protection ODE:	_		ER			
Stator test results:	Salvageable					
Megs incoming: Good	1	Surge incoming:	Good	Hi-pot inc	oming: G	Good
Winding Resistance Inc	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive iml	balance
Incoming 24.56	8	24.583	24.43	36	0.5	
Leads/jumpe If other, leads/jumpe			Lead jur	nper Image. :		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Bearings worn

Cause of Failure

Comments

Motor very rust corroded. Coupling set screws stripped. DE EB shroud has two broken bolts

Service Tech name:

Lynn McDonald

Service Tech signature:

Lyn McDonde

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301