

Job Information

Job #:	94670			Da		September 14, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Curwood		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Decker	Decker Enclosure :	Totally Enclosed Non-Ventilated	Enclosure Type image	
Serial#:		Model#:	Non-ventilated		
Service Factor:		Frame:			
Horsepower/kW:		Rated RPM:			
Rated Amps:		Rated Voltage:			
Phase:		Cycles:			
Special design:	No				

Nameplate

DE

ODE

F1

F2

Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	CCW	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			Not Available

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	Коуо
Insulated:	No	Bearing DE Size:	6310ZZ
Bearings ODE:	Worn	Bearings ODE make:	Коуо
Bearing Type:	Ball	Bearing ODE Size:	6310ZZ
Bearings Retainer:	No	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	Other	Seals Image:	
Seals DE size:	55 75 8		
Seals DE (inbound) condition :	Bad		
Seals ODE type:	Other	Seals Image 2:	C
Seals ODE size:	55 75 8		
Seals ODE (inbound) condition :	Bad		C
Shaft damage cause:	Other	Shaft Image:	



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A



Fan:

N/A

Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

O-rings

Glands

J-Box

Vone

Endbell type:

Single piece

Endbell Image:





Other missing parts

Missing parts?

J-Box cover

HH cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	_	Terminal Markings:				
Length of leads:		REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	_	4-Yellow	8-Red			
Lug type:		Connections As Received:				
Lug Condition:	_	Terminal				
Lug size:						
Lug Attachment:	_	Not Available		Not Available		

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image	Winding Thermal	Protection:	No
Winding condition :	Solid					
Winding Thermal Protection DE:	_		Not Available		N Ava	lot ilable
Winding Thermal Protection ODE:	-			I		
Stator test results:	Rewind					
Megs incoming: Good	b	Surge incoming:	Good	Hi-pot inc	oming: G	Good
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive im	balance
Incoming						
Leads/jumpe	ers: Ok		Lead jur	nper Image. :		
If other, leads/jumpe	ers:				No Availa	it able

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Seal surface need repair on DE AND ODE

Comments

Needs new bearings seals

Service Tech name: Ro

Robert Wiley

Service Tech signature:

 $\Box'Qr$

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301