

Job Information

Job #: 94691 Date: September 14,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Molex Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Open Drop Proof Enclosure Type image

(ODP)
Serial#: A07TESP1111 Model#:

Service Factor: Frame: 449TDZ

Horsepower/kW: 450 Rated RPM: 3570

Rated Amps: 489 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6216 ZZ

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6313 ZZ

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: Thermal Overloads

Lubrication brand inbound: Unknown Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 1/4 Grease Cond. DE: Gritty

Grease Amt ODE: 1/4 Grease Cond. ODE: Gritty

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: Other Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☑ J-Box cover ☐ O-rings ☑ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 24" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Fax 901-873-5301

Lug size:

Lug Attachment:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 28

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type:

Stator condition: Phase-to-phase short If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image:





Yes



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection:

Winding condition: Charred

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:



Conclusion

Component Failure

Windings shorted phase to phase

Cause of Failure

Comments

Windings shorted on coil head appears to be phase to phase, Mechanical checks good, shaft journals are a little oversized, DE coupling fit needs some cleanup coupling gaulded shaft on removal.

LynnMcDonala

Service Tech name: Lynn McDonald

Service Tech signature: