

Job Information

Job #:	94720				Date:	September 13, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Centroid		Reason:		
Contact:		Motor#:		PO#:	
Application:	_	Special notes:			

Name Plate Information

Manufacturer:	SEW	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type im		
Serial#:	S7732934301.0001X 1590	Model#:	RAF67DRS71M4	- Maria		
Service Factor:	1.15	Frame:	RAF67			
Horsepower/kW:	.75	Rated RPM:	1690			
Rated Amps:	7.50/3.25	Rated Voltage:	230/460			
Phase:	3	Cycles:	60			
Special design:	No					

mage



Nameplate

DE

ODE

F1

F2



WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301















MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	NACHI
Insulated:	No	Bearing DE Size:	6303ZZ
Bearings ODE:	Worn	Bearings ODE make:	NSK
Bearing Type:	Ball	Bearing ODE Size:	6203ZZ
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image





CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	0	Grease Cond. DE:	New
Grease Amt ODE:	0	Grease Cond. ODE:	New
Seals DE type:	Other	Seals Image:	
Seals DE size:	17 30 7		
Seals DE (inbound) condition :	Bad		
Seals ODE type:	Slinger	Seals Image 2:	0
Seals ODE size:			
Seals ODE (inbound) condition :			A
Shaft damage cause:	Other	Shaft Image:	

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A

Fan: Ok



Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

J-Box cover

HH cover

J-Box O-rings **V** None Glands

Endbell Image:





Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection


Number of leads:	9	Terminal Markings:	1-9	
Length of leads:		REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Rec	ceived: High voltage	9
Lug Condition:	_	Т	erminal	Lugs
Lug size:		P		
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding c	olor:	Like new	Winding	g image	Winding Therma	al Protection:	No
Winding condit	ion :	Solid					
Winding The Protection		_					
Winding The Protection C		_		7.27			
Stator test res	ults:	Salvageable					
Megs incoming:	Goo	d	Surge incoming:	Good	Hi-pot in	coming:	Good
Winding Resista	ance In	coming					
	Phase	es A to B	Phases B to C	Phase	es C to A	Resistive in	mbalance
Incoming	29.3	89	29.387	29.42	27	0.1	

Leads/jumpers: Ok

If other, leads/jumpers:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

DE SEAL FAILED FILLED MOTOR WITH OIL. GEARBOX OUTPUT SHAFT SEAL SURFACE NEED REPAIR

Comments

Need bearings seals and seal surface repaired

Service Tech name:

Robert Wiley

Service Tech signature:

w Dilley

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301