

Job Information

Job #: 95043 Date: January 8, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Sage Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: TELKOKU Enclosure: Totally Enclosed Enclosure Type image

Non-Ventilated

Serial#: PJ0813A Model#: R42-316F4AM

Service Factor: Frame:

Horsepower/kW: 7.3KW Rated RPM: 3600

Rated Amps: 12 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: Yes

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Thermal Protection

Not Available



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Endbell type: Single piece Missing parts? Endbell Image: Not

✓ None ☐ HH cover Glands

O-rings

Available

Not Available

Other missing parts

☐ J-Box cover

Motor Mount Position:

Horizontal/Foot mount

☐ J-Box



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: — Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

A COLUMN TO THE PARTY OF THE PA





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:

Not Available



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition : Solid

Winding Thermal Not Not Available Available

Winding Thermal ___ Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 1.575 1.572 1.575 0.2

Leads/jumpers: Ok Lead jumper Image. :

Not If other, leads/jumpers: Available



Conclusion

Component Failure

Cause of Failure

Comments

Replace carbon bearings gaskets and orings

Service Tech name: Robert Wiley

Service Tech signature:

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

John Wiley