

### **Job Information**

95738 Job #: Date: July 15, 2019

Priority: Authorized OT: No Authorized by:

# **Customer Information**

Name: ISS Reason:

Contact: Motor#: PO#:

Application: Special notes:

### **Name Plate Information**

1.20

100

No

Manufacturer: **WEG** Enclosure: Open Drop Proof **Enclosure Type image** 

Frame:

QSI

250S/M-02

(ODP) Q-10036ET3F250-Serial#: Model#:

Horsepower/kW: Rated RPM: 3600

Rated Amps: 225/112 Rated Voltage: 230/460

Cycles: Phase: 3 60

Nameplate DE ODE F1 F2 Top



Service Factor:

Special design:











Fax 901-873-5301



present?:

## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: 

Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



## **Mechanical Inspection (Continued)**

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301

CENTRAL ARKANSAS



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:

Ok



Fan: C

Ok

Frame cond.:

Good



1

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





## **Mechanical Inspection (Continued)**

#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

### **AC Electrical Inspection**

Number of leads: — Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug size:

Lug Condition:

Lug Attachment: —

Terminal



Lugs



Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



#### **Rotor Test Results**

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal Protection DE:

Winding Thermal

Protection ODE:

Stator test results: Rewind

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

**Winding Resistance Incoming** 

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image. :



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



### Conclusion

**Component Failure** 

**Cause of Failure** 

Idle bearing failure

**Comments** 

Seize on shaft

Service Tech name:

RHR

Service Tech signature:

Fax 901-873-5301