

Job Information

Job #: 94279 Date: May 23, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Lexicon Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Raul and Enclosure: Totally Enclosed Enclosure Type image

Frame:

WEO-215/H4

Non-Ventilated Serial#: 823471B-3 Model#: 13273

Horsepower/kW: 4 Rated RPM: 1800

Rated Amps: 10.6/5.3 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: Yes

Service Factor:

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Worn

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Carbon

Shaft rotation: — Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

Insulated: No Bearing DE Size: 6306ZZ

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6306ZZ

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

SKF

Not Available Not Available

Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type:

N/A

Seals Image 2:

Not Available

Seals ODE size:

Shaft damage cause: None Shaft Image:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan:

N/A

Frame cond.:

Good

Not Available Not Available



Motor Mount Position:

Horizontal/Flange mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

✓ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

■ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 8" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: 460volt Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: — Available



Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Wound rotor

Other

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Fail Single phase: Fail

Stator type: Factory If other, stator type:

Stator condition: Roast-out If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Charred

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

Stator and rotor rewind, replace slip ring and brushes, sleeve ODE EB

Cause of Failure

Comments

Service Tech name: Lynn McDonald

Service Tech signature:

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301