

Job Information

Job #:	94291				Date:	May 15, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	ConAgra		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Ram Industries	Enclosure :	Open Drop Proof (ODP)
Serial#:	W20002010081-BL	Model#:	N3KBXX244PVHW Z
Service Factor:		Frame:	449TDZ
Horsepower/kW:	437	Rated RPM:	3570
Rated Amps:	482	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2



Тор

RAA Indust















WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Dirt
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE: Worn Bearings DE make: SKF Insulated: Bearing DE Size: 6313 No Bearings ODE: Worn Bearings ODE make: SKF Bearing Type: Bearing ODE Size: Ball 6313 **Bearings Retainer:** Yes Thermal Protection: No Retainer condition: Bad Thermal Protection Type: _

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	-
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Gritty
Grease Amt ODE:	Full	Grease Cond. ODE:	Gritty
Seals DE type:	N/A	Seals Image:	
Seals DE size:			Not Available
Seals DE (inbound) condition :			
		Seals Image 2:	
Seals ODE type:	N/A		Not
Seals ODE size:			Available
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	3000



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A

Fan: N/A Frame cond.: Good







Motor Mount Position:	Horizontal/Fo	ot mount	Endbell type:
Missing parts?			Endbell Image:
J-Box cover	O-rings	J-Box	
HH cover	Glands	None None	

Single piece



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	6	Terminal Markings:		
Length of leads:	22"	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Rea	ceived: 1-6, 2-4, 3-5	5
Lug Condition:	_	ſ	Ferminal	Lugs
Lug size:			Not	1ex
Lug Attachment:	_		ailable	

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Still has color	Winding	g image	Winding Therma	I Protection:	No
Winding condition :	Solid				N	lot
Winding Thermal Protection DE:	_				Avai	lot ilable
Winding Thermal Protection ODE:	_					
Stator test results:	Rewind					
Megs incoming: Bad		Surge incoming:	Bad	Hi-pot in	icoming: E	Bad
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive im	balance
Incoming						
Leads/jumpe	ers: Ok		Lead jur	nper Image. :		
If other, leads/jumpe	ers:				Nc Availi	ot able

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

ODE EB worn, Windings shorted at edge of slots

Cause of Failure

Comments

Heater open will need new (200W 120 VAC)

Service Tech name: Lynn

Lynn McDonald

Service Tech signature:

Jr. Metal

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301