

Job Information

Job #:	94328				Date:	May 21, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	AIT		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Brook Crompton	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type image
Serial#:		Model#:	BC4N010-4	
Service Factor:	1.25	Frame:	215T	
Horsepower/kW:	10	Rated RPM:	1750	
Rated Amps:	26.2/13.2	Rated Voltage:	230/460	The second se
Phase:	3	Cycles:	60	
Special design:	No			

Nameplate

DE

ODE

F1

F2

Тор













WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	_	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	6208ZZ
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6305ZZ
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





Bearing Retainer Image

Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	1/4	Grease Cond. DE:	Other
Grease Amt ODE:	1/4	Grease Cond. ODE:	Other
Seals DE type:	Other	Seals Image:	
Seals DE size:	40-52-7		
Seals DE (inbound) condition :	Fair		
		Seals Image 2:	
Seals ODE type:	Other	Seals inlage 2.	
Seals ODE size:	25-37-7		
Seals ODE (inbound) condition :	Fair		
			100



Shaft Image:

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Shaft damage cause:

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

None



Frame cond.:

Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A

Not Available Fan: Ok



Good

Motor Mount Position: Horizontal/Foot mount Missing parts? J-Box cover O-rings

HH cover

Other missing parts

J-Box None Glands

Endbell type:

Single piece

Endbell Image:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	9	Terminal Markings:			
Length of leads:	12"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	Good	4-Yellow	8-Red		
Lug type:		Connections As Red	ceived: 460 volt		
Lug Condition:	_	I	erminal	Lugs	
Lug size:			Not		
Lug Attachment:	_		ailable		

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum	,	Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:	
Rotor Test Results	5		
Visual: Pass	Growle	er: Pass	Single phase: Pass
Stator type:	Factory	If other, stator ty	be:
Stator condition:	Ok	If other, stator condition	on:
Failure location:	In slot	If other, stator failu	re:
Stator Image:		Failure Ima	^{ge:} Not Available

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image	Winding Thermal	Protection:	No
Winding condition :	Solid				N	lat
Winding Thermal Protection DE:	_				Ava	lot ilable
Winding Thermal Protection ODE:	_					
Stator test results:	Salvageable					
Megs incoming: Good	b	Surge incoming:	Good	Hi-pot inc	coming: C	Good
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive im	balance
Incoming 1.01	7	1.018	1.018	3	0.1	
Leads/jumpe	ers: Ok		Lead jun	nper Image. :	MotorAnalyzer 2	
If other, leads/jumpe	ers:					energia and an

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

DE EB worn, DE Bearing failure

Cause of Failure

Comments

Service Tech name:

Lynn McDonald

Service Tech signature:

pulla ouls 0

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301