

Job Information

Job #: 94352 Date: June 4, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Aim Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Leroy Somer Enclosure : Open Drop Proof Enclosure Type image

(ODP) Serial#: G472245D140001 Model#:

Service Factor: 1.15 Frame: 184TCH

Horsepower/kW: 5 Rated RPM: 1765

Rated Amps: 14/7 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Not

Available

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6207ZZ

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Ball Bearing ODE Size: 6206ZZ

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image Bearing Make Image Bearing Retainer Image Thermal Protection





Not Available Not Available



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/4 Grease Cond. DE: New

Grease Amt ODE: 1/4 Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Not
Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Shaft damage cause:

Seals Image 2:

Seals ODE type: N/A Not Available

Seals ODE size:

Shaft Image:

None



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan: C

Ok

Frame cond.:

Good

Not Available





Motor Mount Position:

Horizontal/Flange mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 6"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 12 AWG P2-Brown

Connections As Received:

2-White 6-No color assigned

460 volt

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Lug type:

Lug Condition: Terminal Lugs

Lug size:

Not Available Lug Attachment:

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 28

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:

Not Available



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal _ Protection ODE:

Stator test results: Salvageable

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 2.471 2.478 2.453 0.7

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

Checks good electrically and mechanically

Cause of Failure

Comments

Service Tech name: Lynn McDonald

Service Tech signature:

Fax 901-873-5301