

Job Information

Job #: 94473 Date: July 2, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: AFT Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Grundfos Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 85902264 Model#:

Service Factor: Frame:

Horsepower/kW: 5 Rated RPM:

Rated Amps: Rated Voltage: 380/415

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top







Not No Available Availa

Not Not Available Available

Fax 901-873-5301

CENTRAL ARKANSAS

Not

Available



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6306ZZ C4

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 7306BF

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Not Available Not Available

Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type:

N/A

Seals Image 2:

Not Available

Seals ODE size:

Shaft damage cause: None Shaft Image:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good

Not Available



Motor Mount Position:

Vertical Flange mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

■ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 6"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: P2-Brown

2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Acceptable







AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

23659

Rotor

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:

Not Available

Fax 901-873-5301

No



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 1.586 1.624 1.659 2.3

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

ODE thrust bearing

Cause of Failure

Lack of lubricant

Comments

Wash, bake and Varnish treat windings

Service Tech name: Lynn McDonald

Service Tech signature:

Phone 901-873-5300 Fax 901-873-5301 Lyn M.Donald