

#### **Job Information**

Job #: 94575 Date: August 13, 2018

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: Delta Plastics Reason:

Contact: Motor#: PO#:

Application: – Special notes:

#### **Name Plate Information**

Manufacturer: Tech Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: SD E918545414002 Model#: AEHH-8N10R

Service Factor: 1.15 Frame: 449T

Horsepower/kW: 300 Rated RPM: 1188

Rated Amps: 347 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301

Not



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes None

> Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Available

Shaft runout(TIR-Inbound): <.001"

Type of grounding device:

Bearings DE: Other Bearings DE make: Other

Insulated: Bearing DE Size: No NU320

Bearings ODE: Other Bearings ODE make: Other

Bearing Type: Bearing ODE Size: Ball 6316

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available



## **Mechanical Inspection (Continued)**

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Labyrinth Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition: Good

Seals ODE type:

Seals Image 2:

Not Seals ODE size: Available

Seals ODE (inbound) condition Good

Shaft damage cause:

Shaft Image:

Fax 901-873-5301

Labyrinth

None



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan: Ok

Frame cond.:

Good

Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

#### **AC Electrical Inspection**

Number of leads: 6 Terminal Markings:

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Not Not Lug Attachment: - Available Available

Fax 901-873-5301

Rotor



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

aug 15

#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



#### Conclusion

**Component Failure** 

Windings grounded

**Cause of Failure** 

Windings grounded at the edge of the stator iron

**Comments** 

Service Tech name: Lynn McDonald

Service Tech signature:

Lyn McLonald