

Job Information

| Job #: | 94584 | | | | Date: | August 15, 2018 |
|-----------|-------|----------------|----|----------------|-------|-----------------|
| Priority: | _ | Authorized OT: | No | Authorized by: | | |

Customer Information

| Name: | Lexicon | | Reason: | |
|--------------|---------|----------------|---------|------|
| Contact: | | Motor#: | | PO#: |
| Application: | _ | Special notes: | | |

Name Plate Information

| Manufacturer: | Rutland | Enclosure : | Totally Enclosed Non-Ventilated | Enclos |
|-----------------|-----------|----------------|------------------------------------|--------|
| Serial#: | 82347A-1 | Model#: | 3888-XH8787C | |
| Service Factor: | | Frame: | MCR-324S | |
| Horsepower/kW: | 20 | Rated RPM: | 1800 | |
| Rated Amps: | 51.2/25.6 | Rated Voltage: | 230/460 | |
| Phase: | 3 | Cycles: | 60 | |
| Special design: | No | | | |

Enclosure Type image



Nameplate





DE



ODE



F1



F2



Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

| Does the shaft turn freely?: | No | Contaminant(s): | None |
|----------------------------------|----|---------------------|------------------|
| Shaft rotation: | _ | Contaminant(s) Amt: | None |
| Shaft grounding device present?: | No | Contaminant Image: | |
| Type of grounding device: | | | Not Available |

Shaft runout(TIR-Inbound):

| Bearings DE: | Worn | Bearings DE make: | FAG |
|---------------------|------|--------------------------|---------|
| Insulated: | No | Bearing DE Size: | 6311 ZZ |
| Bearings ODE: | Worn | Bearings ODE make: | FAG |
| Bearing Type: | Ball | Bearing ODE Size: | 6311 ZZ |
| Bearings Retainer: | No | Thermal Protection: | No |
| Retainer condition: | _ | Thermal Protection Type: | _ |

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Bearing Retainer Image

Thermal Protection

Not Available Not Available



Mechanical Inspection (Continued)

| Lubrication Type: | Grease | Thermal Protection device DE: | - |
|--------------------------------|-------------------|--------------------------------|------------------|
| Lubrication brand inbound: | Mobile Polyrex EM | Thermal Protection device ODE: | _ |
| Lubrication brand outbound: | Mobile Polyrex EM | | |
| Grease Amt DE: | Full | Grease Cond. DE: | New |
| Grease Amt ODE: | Full | Grease Cond. ODE: | New |
| Seals DE type: | N/A | Seals Image: | |
| Seals DE size: | | | Not Available |
| Seals DE (inbound) condition : | | | |
| Seals ODE type: | N/A | Seals Image 2: | Not |
| Seals ODE size: | | | Available |
| Seals ODE (inbound) condition | | | |
| Shaft damage cause: | None | Shaft Image: | |

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A

Fan: N/A Frame cond.:

Good







Single piece

| Motor Mount Position: | Horizontal/Foo | ot mount | Endbell type: |
|-----------------------|----------------|-----------|----------------|
| Missing parts? | | | Endbell Image: |
| J-Box cover | O-rings | J-Box | |
| HH cover | Glands | None None | |
| | | | |

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Other missing parts



Mechanical Inspection (Continued)

| Air Gap Meaurements (N/A on Single Piece Endbell) | | | Does Air Gap Meet Customer or EASA spec(<10% variation)? |
|---|----------|-----------|--|
| | DE @ 0 | ODE @ 0 | _ |
| | DE @ 90 | ODE @ 90 | |
| | DE @ 180 | ODE @ 180 | |
| | DE @ 270 | ODE @ 270 | |

AC Electrical Inspection

| Number of leads: | 6 | Terminal Markings: | | |
|------------------|------|-----------------------------------|---|----------------------------------|
| Length of leads: | 12" | REF: NEMA Std Markings Identif | s. MG 1-2009, Rev. 1- ied By Color: | -2010, 2.41-Terminal |
| Size of leads: | | 1-Blue 2-White 3-Orange | 5-Black 6-No color assigned 7-No color assigned | P1-No color assigned P2-Brown |
| Lead condition: | Good | 4-Yellow | 8-Red | |
| Lug type: | | Connections As Re | ceived: | |
| Lug Condition: | - | | Terminal | Lugs |
| Lug size: | | | Not | 1 RA |
| Lug Attachment: | _ | Av | ailable | |

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



.

AC Electrical Inspection (Continued)

| Rotor Type: | Wound rotor | | Rotor |
|---|-------------|-------------------------------------|--------------------|
| Rotor Condition: | Other | Num rotor bars: Num broken bars: | |
| Rotor Test Results Visual: Fail | Growle | er: Fail | Single phase: Fail |
| Stator type: | HISI | If other, stator ty | pe: |
| Stator condition: | Ok | If other, stator condition | on: |
| Failure location: | Core edge | lf other, stator failu | ire: |
| Stator Image: | | Failure Ima | ge: |

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

| Winding color: | Still has color | Winding | g image | Winding Therma | I Protection: | Yes |
|------------------------------------|-----------------|-----------------|----------|----------------|---------------|------------|
| Winding condition : | Solid | | | | N | lot |
| Winding Thermal Protection DE: | _ | | And A | | Avai | lable |
| Winding Thermal Protection ODE: | _ | | | | | |
| Stator test results: | Rewind | | | | | |
| | | | | | | |
| Megs incoming: Bad | | Surge incoming: | Bad | Hi-pot in | coming: B | ad |
| Winding Resistance In | coming | | | | | |
| Phase | es A to B | Phases B to C | Phase | es C to A | Resistive im | balance |
| Incoming | | | | | | |
| | | | | | | |
| Leads/jumpe | ers: Ok | | Lead jur | nper Image. : | | |
| If other, leads/jumpe | ers: | | | | Nc Availa | ot able |

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Stator windings bad rotor windings bad, ODE EB housing needs relief

Cause of Failure

Windings shorted to ground

Comments

Service Tech name: Lynr

Lynn McDonald

Service Tech signature:

Lyn Mill m JA

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053

Phone 901-873-5300

Fax 901-873-5301

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

CENTRAL ARKANSAS