

Job Information

Job #:	94547				Date:	August 2, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Flakeboard	Motor#:

Name Plate Information

Siemens	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	60 Hp
F04T014DEV9	Model#:	1LA93644FP21	Service Factor:	1.15
364T	Rated RPM:	1775	Rated Voltage:	230/460
3	Rated Amps:	142/70.8	Cycles:	60
	F04T014DEV9 364T	F04T014DEV9 Model#: 364T Rated RPM:	Fan Cooled F04T014DEV9 Model#: 1LA93644FP21 364T Rated RPM: 1775	Fan CooledF04T014DEV9Model#:1LA93644FP21Service Factor:364TRated RPM:1775Rated Voltage:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Damaged	Bearings Retainer:	No
Type of grounding device:		Bearing DE Size:	6314 Z
Shaft runout(TIR-Inbound):	<.002	Bearing ODE Size:	6210 Z

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254





Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	5.9071	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gan Meet Cu	stomer or EASA spec(<10%
Endbell ODE size:	3.5455	variation)?	
Endbell ODE insulated?:	No	_	

Conclusion

Service Tech name:

Lynn McDonald

Service Tech signature:

Lynn McDonald

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254