

### **Job Information**

Job #:	94788				Date:	October 23, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

### **Customer Information**

Name:	Sage	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

No

Manufacturer:	SWECO	Enclosure :	Totally Enclosed Non-Ventilated
Serial#:	EF5T46668N- F4-42-01118	Model#:	
Service Factor:	1.0	Frame:	143TZX
Horsepower/kW:	.5	Rated RPM:	1160
Rated Amps:	1.45	Rated Voltage:	460
Phase:	3	Cycles:	60

#### Enclosure Type image



Nameplate

Special design:


ODE

F1

F2















WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	22308
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Roller	Bearing ODE Size:	NU307EC
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

#### Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	Other	Seals Image:	
Seals DE size:	34 45 5		0
Seals DE (inbound) condition :	Bad		Y
		Seals Image 2:	
Seals ODE type:	Other	Jeals intage 2.	
Seals ODE size:	34 45 5		0
Seals ODE (inbound) condition :	Bad		

Shaft damage cause:

None

#### Shaft Image:



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Brg. Image:	Bushings/sle	eves image: Not Available
Water jacket: N/A	Fan: N/A Not Available	Frame cond.: Good
Motor Mount Position: Horizontal/Foot mount   Missing parts? J-Box cover   J-Box cover O-rings   HH cover Glands   Other missing parts	Endbell Image:	Endbell type: Single piece

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


## **AC Electrical Inspection**

Number of leads:	3	Terminal Markings:	1-3				
Length of leads:	32"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:					
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown			
Lead condition:	Good	4-Yellow	8-Red				
Lug type:		Connections As Received:					
Lug Condition:	_	т	erminal	Lugs			
Lug size:							
Lug Attachment:	_	Av	Not ailable	Not Available			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding color:	Like new	Winding	g image	Winding The	rmal Protecti	ion:	No
Winding condition :	Solid						
Winding Thermal Protection DE:	-					No Avail	ot able
Winding Thermal Protection ODE:	_						
Stator test results:	Rewind						
Megs incoming: Go	bod	Surge incoming:	Good	Hi-po	ot incoming:	Go	od
Winding Resistance In	coming						
Phase	es A to B	Phases B to C	Phases	s C to A	Resistiv	/e imba	alance
Incoming 24.4	22	24.427	24.39	1	0.1		
Leads/jumpe	ers: Ok		Lead	jumper Imag	e. :		
If other, leads/jumpe	ers:						Not iilable
Mechanical Ins	pection						
Inspect bolt holes and fa	asteners. Valida	te correct fasteners.					
Shaft Conc	dition: Good		Bearings	Retainer:	No		
Type of grounding de	evice: NA		Bearing	g DE Size:	22308		
Shaft runout(TIR-Inbo	und):		Bearing (	ODE Size:	NU307EC		
Retainer conc	dition: —						

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	Other	If DE undersized, amt.:	
Seals DE size:	34 45 5	Brg. Seats ODE:	Good
Seals DE (inbound) condition :	Bad	If ODE undersized, amt.:	
Seals ODE condition :	Other	Shaft damage:	ОК
Seals ODE type:	Other		
Seals ODE size:	34 45 5	Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :	BAD	Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.5429	Foot flatness:	Pass
Endbell DE insulated?:	No		stomer or EASA spec(<10%
Endbell ODE size:	3.1493	variation)?	
Endbell ODE insulated?:	No		

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

**Component Failure** 

**Cause of Failure** 

Comments

De Bearing And SEAL FAILED DUE TO WATER

Service Tech name:

Robert Wiley

Service Tech signature:

52 Wiles

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301